Rapid Ordinary High Water Mark Field Identification Datasheet Photo Log:

Figure 1: Photo 1. Northwest culvert facing Zuckerman Ave.

Figure 2: Photo 2. Sandy Soil Profile within dry portions of channel bed. Munsell color of 10YR 4/4

Figure 3: Photo 3. Clay soil profile in ponded portions of channel bed. Munsell color of 2.5 YR 5/8

Figure 4: Photo 4. Image of stream channel with leaf litter debris looking towards Bjronstadt St.

Figure 5: Photo 5. Leaf litter buildup

Figure 6: Photo 6. Water stained leaves

Figure 7: Photo 7. Standing water within channel bed

Figure 8: Photo 8. Bar in channel looking towards Bjornstadt St.

Figure 9: Photo 9. Break in bank slope/Embankment scarp

Figure 10: Photo 10. Image showing undercutting of large tree along channel bank